

# STATE OF TEXAS WELL REPORT for Tracking #384301

Owner:	Don Freeman	Owner Well #:	No Data
Address:	P.O. Box 175 Llano, TX 78643	Grid #:	57-11-2
Well Location:	145 Horse Mountain Trail; .2 mi. S below pond TX	Latitude:	30° 50' 38" N
		Longitude:	098° 40' 45" W
Well County:	Llano	Elevation:	No Data
Type of Work: <b>New Well</b>		Proposed Use: <b>Stock</b>	

Drilling Start Date: **12/22/2014**      Drilling End Date: **12/22/2014**

	Diameter (in.)	Top Depth (ft.)	Bottom Depth (ft.)
Borehole:	<b>9</b>	<b>0</b>	<b>37</b>
	<b>6.75</b>	<b>37</b>	<b>38</b>
	<b>6</b>	<b>38</b>	<b>60</b>

Drilling Method: **Air Hammer**

Borehole Completion: **Open Hole**

	Top Depth (ft.)	Bottom Depth (ft.)	Description (number of sacks & material)
Annular Seal Data:	<b>1</b>	<b>3</b>	<b>1 Cement</b>
	<b>3</b>	<b>37</b>	<b>5 Bentonite</b>

Seal Method: **Grout**

Sealed By: **Driller**

Distance to Property Line (ft.): **No Data**

Distance to Septic Field or other concentrated contamination (ft.): **No Data**

Distance to Septic Tank (ft.): **No Data**

Method of Verification: **No Data**

Surface Completion: **Pitless Adapter Used**

Water Level: **30 ft.** below land surface on **2014-12-22**      Measurement Method: **Unknown**

Packers: **No Data**

Type of Pump: **Submersible**      Pump Depth (ft.): **50**

Well Tests: **Jetted**      Yield: **20 GPM**

Water Quality:	<i>Strata Depth (ft.)</i>	<i>Water Type</i>
	<b>40, 47, 50</b>	<b>good (310 ppmTDS)</b>

Chemical Analysis Made: **No**

Did the driller knowingly penetrate any strata which contained injurious constituents?: **No**

Certification Data: The driller certified that the driller drilled this well (or the well was drilled under the driller's direct supervision) and that each and all of the statements herein are true and correct. The driller understood that failure to complete the required items will result in the report(s) being returned for completion and resubmittal.

Company Information: **Virdell Drilling Inc.**  
**111 E. Grayson St.**  
**Llano, TX 78643**

Driller Name: **James Caleb Virdell** License Number: **59342**

Comments: **No Data**

Lithology:  
DESCRIPTION & COLOR OF FORMATION MATERIAL

Casing:  
BLANK PIPE & WELL SCREEN DATA

<i>Top (ft.)</i>	<i>Bottom (ft.)</i>	<i>Description</i>
<b>0</b>	<b>2</b>	<b>Topsoil</b>
<b>2</b>	<b>15</b>	<b>Brown Clay &amp; Gravel</b>
<b>15</b>	<b>36</b>	<b>Weathered Black Metamorphic</b>
<b>36</b>	<b>60</b>	<b>Red &amp; Black Metamorphic</b>

<i>Dia. (in.)</i>	<i>New/Used</i>	<i>Type</i>	<i>Setting From/To (ft.)</i>
<b>6"</b>	<b>N</b>	<b>PVC +2 - 38 sch 40</b>	

**IMPORTANT NOTICE FOR PERSONS HAVING WELLS DRILLED CONCERNING CONFIDENTIALITY**

TEX. OCC. CODE Title 12, Chapter 1901.251, authorizes the owner (owner or the person for whom the well was drilled) to keep information in Well Reports confidential. The Department shall hold the contents of the well log confidential and not a matter of public record if it receives, by certified mail, a written request to do so from the owner.

Please include the report's Tracking Number on your written request.

**Texas Department of Licensing and Regulation**  
**P.O. Box 12157**  
**Austin, TX 78711**  
**(512) 334-5540**