STATE OF TEXAS WELL REPORT for Tracking #524175						
Owner:	Lewis Durst	Owner Well #:	No Data			
Address:	1397 E State Hwy 29 Llano, TX 78643	Grid #:	57-19-5			
Well Location:		Latitude:	30° 40' 09.97" N			
		Longitude:	098° 40' 33.47" W			
Well County:	Llano	Elevation:	No Data			
Type of Work:	New Well	Proposed Use:	Domestic			

Drilling Start Date: 10/2/2019 Drilling End Date: 10/2/2019

	Diameter (in.) Top Depth		(ft.) Bo	ottom Depth (ft.)		
Borehole:	9	0		27		
	6.25	27		185		
Drilling Method:	Air Hammer; Air Rotary					
Borehole Completion:	etion: Open Hole					
	Top Depth (ft.)	Bottom Depth (ft.)	Description (nu			
Annular Seal Data:	-2	4	Cemen			
	4	27	Bentoni	Bentonite 4 Bags/Sacks		
Seal Method: Po	oured	Distar	nce to Property Lir	ne (ft.): <b>50+</b>		
Sealed By: Dr	iller	Distance to Septic Field or other concentrated contamination (ft.): <b>No Data</b>				
		Dist	ance to Septic Ta	nk (ft.): <b>No Data</b>		
			Method of Verifi	cation: <b>No Data</b>		
Surface Completion:	npletion: Surface Sleeve Installed		Surface Completion by Driller			
Water Level:	31 ft. below land	surface on 2019-10-02	Measurement	Method: Steel Tape		
Packers:	No Data					
Type of Pump:	No Data					
Well Tests:	Jetted	Yield: 20.56 GPM				

	Strata Depth (ft.)	Water Type		
Water Quality:	120	No Data		
		Chemical Analysis Made:	No	
	Did the driller kr	nowingly penetrate any strata which contained injurious constituents?:	Νο	
Certification Data:	driller's direct supervisi correct. The driller und	t the driller drilled this well (or the we on) and that each and all of the state derstood that failure to complete the irned for completion and resubmittal	ements here required ite	ein are true and
Certification Data: Company Information	driller's direct supervisi correct. The driller und the report(s) being retu	on) and that each and all of the state derstood that failure to complete the	ements here required ite	ein are true and
	driller's direct supervisi correct. The driller und the report(s) being retu	on) and that each and all of the state derstood that failure to complete the irned for completion and resubmittal	ements here required ite	ein are true and
	driller's direct supervisi correct. The driller und the report(s) being retu Magill Drilling & Wa PO Box 46	on) and that each and all of the state derstood that failure to complete the irned for completion and resubmittal	ements here required ite	ein are true and

## Lithology: DESCRIPTION & COLOR OF FORMATION MATERIAL

Casing: BLANK PIPE & WELL SCREEN DATA

Top (ft.)	Bottom (ft.)	Description	Dla (in.)	Туре	Material	Sch./Gage	Top (ft.)	Bottom (ft.)
0	1	Topsoil Red Sandy Clay		Blank	New Plastic (PVC)	40	-2	27
1	27							
27	185	Gray Granite						

## IMPORTANT NOTICE FOR PERSONS HAVING WELLS DRILLED CONCERNING CONFIDENTIALITY

TEX. OCC. CODE Title 12, Chapter 1901.251, authorizes the owner (owner or the person for whom the well was drilled) to keep information in Well Reports confidential. The Department shall hold the contents of the well log confidential and not a matter of public record if it receives, by certified mail, a written request to do so from the owner.

Please include the report's Tracking Number on your written request.

Texas Department of Licensing and Regulation P.O. Box 12157 Austin, TX 78711 (512) 334-5540